

ARCS PROCEDURE:	COPYING WSI HEADER FILES TO FLOPPY	PRO(WSI)-015.001
Author: P. Malone		February 16, 2001 Page 1 of 2

WSI – Copy Header Files to Floppy

I. Purpose:

To describe the commands used for copying the WSI header files to floppy.

II. Cautions and Hazards:

None.

III. Requirements:

- Floppy disk.

IV. Procedure:

A. Steps:

1. Go to the I-Van and look at the blue box. Bring along a new blank floppy.
2. Press the 'x' key. You will get a c:\runwsi
3. Open the door of the blue box. On the right side there is a key that will open up to 2 floppy drives. Find the floppy drive labeled (bottom one) WSI.
4. Insert the floppy disk into the WSI floppy drive.
5. Type the following commands:
copy header0.dgn a:
copy header1.dgn a:
dir a:
Do you see the header0.dgn and header1.dgn files listed? If yes go to step 6. If no repeat step 5 and check for spelling errors.
6. Remove the floppy disk and shut the floppy drive door and the blue box door.
7. Type **runwsi** (the picture will come back up).
8. Take the floppy disk over to the observer computer and insert it.
9. Click on the My Computer icon.
10. A window should come up. Click on the floppy (A:) icon
11. A window will appear and you will see the header0.dgn and header1.dgn files appear in the window.

ARCS PROCEDURE:	COPYING WSI HEADER FILES TO FLOPPY	PRO(WSI)-015.001
Author: P. Malone		February 16, 2001 Page 2 of 2

12. Select each file and print it out. Fax it to TWPPO.

V. References:

None.

VI. Attachments:

None.